

Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-020	Smoke	8/12/2008	ADS/TM	S09SS_009MH	Dry	Yes	1,391.71



Smoke and Dye Testing Summary

High Level Sewershed

Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-020	Smoke	8/12/2008	ADS/TM	S09SS_009MH	Dry	Yes	1,391.71

Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S09SS_005G1	S09SS_005MH	S09SS_006MH	162.3405	8
S09UU_008G1	S09UU_008MH	S09SS_009MH	249.4396	8
S09SS_011G1	S09SS_011MH	S09UU_010MH	177.2901	8
S09SS_009G1	S09SS_009MH	S09SS_003MH	40.22752	999
S09UU_005G1	S09UU_005MH	S09UU_008MH	307.2848	8
S07UU_011G1	S07UU_011MH	S09UU_005MH	143.6130	8
S09SS_003G1	S09SS_003MH	S09SS_005MH	141.7413	8
S09SS_006G1	S09SS_006MH	S09SS_011MH	169.7765	8

Observations & Photos

Obs_ID S1028-020-OB01

Address 3501 Fairview Ave

Status Private

Source Cleanout

Location Yard - front

Nearest MH S07UU_011MH

Comments Smoke from cleanout in front yard. 3501 Fairview Ave.



Picture \S1028-020-OB01-P01.jpg

Comments Front of house, 3501 Fairview Ave.

Obs_ID S1028-020-OB02

Address 3308 Fairview Ave


Status Private

Source Cleanout

Location Yard - front

Nearest MH S09SS_009MH

Comments Smoke from cleanout in front yard. 3308 Fairview Ave.



Picture \S1028-020-OB02-P01.jpg

Comments Front of house, 3308 Fairview Ave.